



Pennsylvania Department of Environmental Protection

208 West Third Street, Suite 101
Williamsport, PA 17701-6448

~~November 12, 2008~~

Northcentral Regional Office

RECEIVED

Fax 570-327-3420

NOV 17 2008

ENVIRONMENTAL PROTECTION
NORTHWEST REGIONAL OFFICE

Re: Act 223, Section 208 Determination
Complaint No. 259175
Clymer Twp., Tioga County

Dear

The Department has investigated the degradation of your water supply in response to your October 20, 2008, complaint that recent gas well drilling activities conducted by Dominion Transmission, Inc. had affected your spring.

On October 22, 2008, the Department collected water samples from the spring at your property and from the spring outfall at Mill Creek. The analytical reports for these samples are included, as well as documents that will assist you with interpreting the sample results. The sample results indicate, and therefore the Department has determined, that your water supply has been affected by drilling activities conducted by Dominion Transmission, Inc.

The Department understands that Dominion Transmission, Inc. will continue to provide you with potable water at your residence until the quality of your spring has returned to acceptable conditions or until your water supply has been permanently restored or replaced. The Department continues to work with Dominion Transmission, Inc. in an effort to resolve this matter.

In the meantime, if you have any questions or concerns, please call me at 570-327-0535.

Sincerely,

Richard F. Hall
Water Quality Specialist
Oil and Gas Management

cc: A. Oprende
NWRO File





Pennsylvania Department of Environmental Protection

208 West Third Street, Suite 101

Williamsport, PA 17701-6448

April 28, 2009

Northcentral Regional Office

Fax 570-327-3420

Re: Act 223, Section 208 Determination
Complaint No. 259175
Clymer Twp., Tioga County

Dear

The Department has investigated the degradation of your water supply in response to your October 20, 2008, complaint that recent gas well drilling activities conducted by Dominion Transmission, Inc. (Dominion) had affected your spring.

Water samples collected from your spring on October 22, 2008 indicated that your water supply was affected by drilling activities conducted by Dominion. Remedial measures were implemented by Dominion in response to the pollution incident. On April 1, 2009, the Department collected both pre-treatment and post-treatment water samples from your spring. Analytical data indicates that all of the targeted parameters are below the PADEP Maximum Contaminant Levels (MCLs) for both the pre-treatment and the post-treatment samples.

Based on available analytical data, the Department has determined that the quality of your spring has returned to acceptable conditions. If you have any additional questions or concerns, please call me at 570-327-0535.

Sincerely,

Richard F. Hall
Water Quality Specialist
Oil and Gas Management

cc: Jennifer W. Means
A. Oprendeck
NCRO File
Dominion Transmission, Inc.