




# GOOD MECHANICAL INTEGRITY



# CEMENT CHANNELING



# LEAK THROUGH CASING



# INSUFFICIENT CEMENT COVER

